

Fig. 1 shows the typical situation on ships around the world.

OWS has large daily operational problems because the bilge tank is too dirty

Much water in the sludge tank, give frequent sludge deliveries to port and large bills




fig. 1

The GreenArc 500 Bilge & Sludge system can take your ship from the situation fig. 1 to fig. 2 without the use of filters or chemicals and with only two moving parts. A highly reliable system that removes up to 99% of your bilge and sludge problems.

Flow diagram of the system, shows how this is done. It is an Internal cleaning.




fig. 2

DNV-GL Approved Pre-separator system !